

Dolphin Yachts S.L. Club de Mar 07015 Palma de Mallorca Spain info@dolphin-yachts.com



## Lagoon 570

Builder: Lagoon LOA: 16.80m (55'1") Model: 570 Beam: 9.14m (30'0") 2006 1.43m (4'7") Year: Draft: Construction: **GRP** Fuel: 1.408 Litres

Accommodation: 8 berths in 4 cabins Water: 700 Litres

Designer: Peteghem & Prevost Engines: 2 x 75hp Volvo Penta

Displacement: 14000 kg Keel: Multihull

580.000 US\$ EU VAT not paid

Tel: +34 971 700844 Fax: +34 971 702275 Mobile: +34 609 622313

www.dolphin-yachts.com

## Dolphin Yachts S.L.

Tel: +34 971 700844

Web: www.dolphin-yachts.com



#### **ENGINE:**

2 x 75hp Volvo Penta D2-75B Turbodiesel

Engine Hours: 1730 aprox.

#### SPEED:

9 knots aprox.

### **CAPACITIES:**

Fuel: 1408 Litres Water: 700 Litres Holding: 302 Litres

## MECHANICAL EQUIPMENT:

Onan MDKBN 12kW generator (1600 hrs January 2015)

Searecovery SRC 1400-2AWC watermaker, 180 litres/h (2 membranes)

Two water tanks built into keels with electrical gauge, 500 litres + 200 litres

Two holding tanks, 151 litres each

Two hot water heaters Quick 1200W (plus hot water from engines), 83 litres each

Electrical sump pump for each shower

Three fuel tanks, 2x 454 litres + 1x 500 litres

Two interconnecting 12V pressure water systems

Bilge draining system including four hand pumps, four electrical pumps with two float switches

Shore power with 15m cable

Two Mastervolt Mass 12/80 chargers

Two alternators (one on each engine)

Electrical sockets 220V (two in every cabin, six in master cabin, many in saloon and galley)

Two 3000W Cotek CR-6 inverters

Mastervolt Battery Monitor BTM III system

Two Volvo Penta 150S-B v2.19 sail drives

Two three-bladed fixed propellers

## **ACCOMMODATION:**

Berths: 8 Cabins: 4 Head: 4

Crew Berths: 0 Crew Cabins: 0

Four cabins, all en-suite with WC/shower

Two cabins forward, each with single upper and lower berths

Two cabins aft, each with double berth

Each cabin has an independent molded washroom unit with:

Pressurized shower with hot and cold water mixer tap

White molded fiberglass furnishings with toilet paper holder and access to thru-hulls

Sink, towel holder, two hooks

Large bowl manual marine toilet

Teak shower grate

Storage cabinet above sink with enlightened mirrors

## ACCOMMODATION EQUIPMENT:

Enormous saloon with dining area to port and main saloon to starboard

Central chart table facing forward with rotating pedestal seat and gooseneck reading light

Electrical panel and access to connections

Two wooden tables, one for dining, the other for the saloon with integrated bar locker

Four opening hatches forward

## Dolphin Yachts S.L.

Tel: +34 971 700844

Web: www.dolphin-yachts.com



Two opening roof hatches

White lacquered aluminium sliding glass door with lock for cockpit access

White lacquered aluminium sliding glass window with lock for cockpit access

Leathered stainless steel guardrail in the dining area

Six folding chairs

Flat screen TVs (saloon, cabins)

## GALLEY/LAUNDRY:

Two Frigoboat Frigomatic K50 F refrigerators

Double sink s/s

Stove with two inductions + two electric rings

Microwave oven

Laminate counter tops

Stowage under sinks, with shelves and access to thru-hulls

Saltwater pump for deckwash

Washing machine

#### **NAVIGATION:**

Raymarine GPS

Two Raymarine ST60+ Tridata depthsounder

Two RaymarineST60+Wind wind speed and direction + three ST60+ graphic displays

Two Raymarine ST7002 + two ST6002 autopilots

Raymarine Ray54E VHF radio

Iridium 9505A SatPhone system

Raymarine radar

Raymarine E120 chart plotter

Two Plastimo compasses

#### DECK:

Deck cleats: 6x Spinlock CAM-0814 + 7x Spinlock XX0812

Winches: 4x Harken 60.2 electric + 2x Harken 53 electric + 2x Harken 53 manual 1500W electrical windlass (12mm gipsy) in anchor locker with up/down remote

Stainless steel anchor

Two lockers located forward of the mast with stainless steel spring supports

Port side locker for generator or storage

Starboard locker for windlass, storage, watertight gas bottle

Wide cockpit, usable as an outdoor saloon

Twin ergonomic steering stations with sheathed wheels, helm seat, engine controls on port side, engine control panels, compass

Teak cockpit table with folding leaves, protection cover

Teak strip cockpit floor

L-shaped cockpit bench seat with two lockers on starboard side

Straight cockpit bench seat with locker to port

Two large cockpit storage compartments

Four large cockpit storage compartments aft

Foam cockpit seat and backrest cushions on bench seats

Cockpit storage locker on port side

Teak strips on transom

Hinged engine access panel with hydraulic lifter in first step of transom

Two hot/cold sweet water deck showers built-in on starboard and port side of transom

Three steps to access retractable swim ladder on port and starboard sides of transom

Storage locker in last step of transom

Retractable swim ladder on each transom

Retractable diving ladder on transom

Bimini top

## Dolphin Yachts S.L.

Tel: +34 971 700844

Web: www.dolphin-yachts.com



## SPARS & SAILS:

Sloop rigged - Fully roached Dacron double-ply mainsail 104 sqm (2007) with epoxy/glass extruded full-length battens mounted on roller bearing cars for perfectly easy sail handling (triple-sewn seams, aluminum reinforced headboard, three reef points, etc.)

Double-ply Dacron furling genoa 92 sqm with reinforced leech and UV protection Double-ply Dacron furling staysail 26 sqm with reinforced leech and UV protection Symmetrical spinnaker 190 sqm

Furling asymmetrical gennaker 126 sqm

Furling jib 68 sqm

## Standing rigging:

White lacquered aluminum mast with welded fittings (mast clearance: 24,27m)

White lacquered aluminum boom

Double swept-back spreaders

Track with roller bearing cars for fully-battened mainsail

Forestay with furler for genoa Babystay with furler for staysail Two sheathed cap shrouds

Two sheathed lower shrouds

## Running rigging:

Mainsail halyard with 2:1 purchase

Genoa halyard Staysail halyard

Pre-stretched mainsail topping lift

Pre-stretched mainsail outhaul with hoist

Three pre-stretched mainsail reefing control lines

Pre-stretched mainsheet

Two genoa sheets

Staysail sheet

Two mainsail traveler control lines

Genoa furler line

Staysail furler line

Set of lazy jacks on boom

#### SAFETY:

Plastimo liferafts (2)

## TENDERS/TOYS:

Zodiac Zoom 350 SP ALU 3.50m dinghy with aluminium floor (November 2012) Tohatsu 9.8hp 2-stroke engine (December 2014)

## SERVICE HISTORY AND CONSTRUCTION:

Hulls and nacelles are fiberglass sandwich laminate (balsa sandwich) vacuum-bag infusion with polyester and vinylester resins, white gelcoat

Deck is fiberglass sandwich laminate (balsa sandwich), vacuum-bag infusion with vinylester resin Bulkheads are fiberglass sandwich laminate (balsa sandwich) vacuum-bag infusion with vinylester resin Construction specifications follow the highest standards of composite material manufacturing: multi-directional fiberglass fabric, carbon-fiber reinforcement, resin-impregnated marine-grade plywood

All bulkheads and structural bonding are made with bi-directional woven glass cloth Bridge clearance: 24.32m

## **BROKERS COMMENTS:**

The **Lagoon 570** is an impressive jewel with modern design and outstanding sailing performance. She sleeps eight guests in four en-suite cabins and is in excellent condition. Although she was built in 2006,

## Dolphin Yachts S.L. Tel: +34 971 700844

Web: www.dolphin-yachts.com



she was actually first launched in Summer 2007 (semi-owner option). A world-class yacht ready to set sail on a world-class cruise.

LYING:

Caribbean

# Dolphin Yachts S.L. Tel: +34 971 700844 Web: www.dolphin-yachts.com
















Web: www.dolphin-yachts.com



## **Layout Plans**



The particulars presented in this brochure are based on information provided by the sellers and are believed to be correct, although we cannot be liable for any inaccuracy. A prospective buyer is strongly advised to check these particulars and where appropriate and at his own expense to employ a qualified marine surveyor and / or have an engine trial conducted which if conducted by us shall not imply any liability on our part.