

Dolphin Yachts S.L. Club de Mar 07015 Palma de Mallorca Spain info@dolphin-yachts.com



Tiara 4400 Sovran

Builder: Tiara LOA: 15.34m (50'3") 4400 Sovran Model: Beam: 4.42m (14'5") 1.37m (4'5") Year: 2005 Draft: Construction: **GRP** Fuel: 1.991 Litres Accommodation: 6 berths in 2 cabins 568 Litres Water:

Designer: Tiara Yachts Engines: 2 x 715hp Caterpillar

Displacement: 15037 kg Speed: 30 Knots

200.000 € EU VAT paid

Tel: +34 971 700844 Fax: +34 971 702275 Mobile: +34 609 622313 www.dolphin-yachts.com

Dolphin Yachts S.L.

Tel: +34 971 700844

Web: www.dolphin-yachts.com



ENGINE:

2 x 715hp Caterpillar C-12 Engine Hours: 260 aprox.

SPEED:

Top: 30 knots aprox. Cruise: 25 knots aprox.

CAPACITIES:

Fuel: 1991 Litres Water: 568 Litres Holding: 189 Liters

MECHANICAL EQUIPMENT:

Twin 715hp Caterpillar C-12 diesel main engines, V-drive type gearbox, Aquamet prop shafts, PSS shaft seals, two Nibral 4-bladed props, Glendinning single-lever engine controls, Teleflex hydraulic steering system with 22" steering wheel, Racor fuel filters for engines and generator

Central vacuum system (guest cabin)

Marine Air Systems reverse cycle airconditioning/heating throughout with 3 units (saloon, master and guest cabin)

Sealand Vacuflush electric toilet system connected to holding tank

Two Sterling Power 24v-30A battery chargers

Volvo bowthruster

Onan 11,5kW generator

220V electrical circuit

Shore power inlet

Five electric bilge pump with monitors at helm position

Fresh water pressure system

Water heater

ACCOMMODATION:

Berths: 6 Cabins: 2 Head: 2

Crew Berths: 0 Crew Cabins: 0

Teak interior finish, teak hardwood floor, spacious two cabin layout

Master cabin forward with queen-size pedestal bed and en-suite wc/shower

Guest cabin with two overlapping bunk-style beds to starboard aft with en-suite head and washing machine

Saloon with a folding birds-eye maple/teak table which converts to berth, increasing sleeping accommodations to 6 (seating between 4-5 around dining table when converted to U-shaped seating area)

ACCOMMODATION EQUIPMENT:

Sharp 22' flat screen LCD TV in saloon Sharp Aquos 13" flat screen LCD TV in master cabin Bose Lifestyle stereo with CD, integrated DVD and speakers Clarion radio

GALLEY/LAUNDRY:

Corian countertops Stainless steel sink Kenyon vitro-ceramic two-plate cooker Tappan microwave

Dolphin Yachts S.L.

Tel: +34 971 700844

Web: www.dolphin-yachts.com



Two Isotherm fridges with freezer compartment Combination washer/dryer (guest cabin)

NAVIGATION:

Compass Simrad AP26 autopilot VHF radio Depthsounder Raymarine radar GPS Raymarine C120 plotter

DECK:

Companion lounge with table and wet bar Workable side decks
Foredeck sunpad
Cockpit cushions
Electric windlass
Cockpit speakers
Cockpit shower
Gangway
Swimming platform
Swimming ladder
Hydraulic rear trunk for storage

SAFETY:

Seafire FM-200 automatic fire extinguisher in engine room Viking 6-person liferaft

BROKERS COMMENTS:

This well USA built innovative **Tiara 4400 Sovran** is CE marked and has only had one owner from new. Her cockpit includes an extremely functional integral hardtop and is very flexible given the hydraulic table which rises from the deck with the flip of a button. The helm deck seating offers an electrically adjustable double helm seat and companion lounge with table and wet bar. Below decks, the 4400 features plush leather seating, full reverse cycle air con, Corian countertops and built-in flat screen TVs. The lounge includes a folding bird's eye maple/teak table which converts to a berth, increasing sleeping accommodation to six. The master cabin boasts a queen-size pedestal bed and the guest cabin not only comes with two overlapping bunk style beds, but also with a washer/dryer combination and its own access to the bathroom. All this, together with only 260 engine hours, makes her a great opportunity!

LYING:

Spain
















Web: www.dolphin-yachts.com



Layout Plans



The particulars presented in this brochure are based on information provided by the sellers and are believed to be correct, although we cannot be liable for any inaccuracy. A prospective buyer is strongly advised to check these particulars and where appropriate and at his own expense to employ a qualified marine surveyor and / or have an engine trial conducted which if conducted by us shall not imply any liability on our part.