

Dolphin Yachts S.L. Club de Mar 07015 Palma de Mallorca Spain info@dolphin-yachts.com

Oyster 68

 Builder:
 Oyster
 LOA:
 20.57m (67'5")

 Model:
 68
 Beam:
 5.26m (17'3")

 Year:
 1989
 Draft:
 2.36m (7'7")

Construction: GRP Fuel: 2 tons
Accommodation: 10 berths in 5 cabins Water: 2 tons

Designer: Holman & Pie Engines: 1 x 160hp Perkins

Displacement: 39462 kg Keel: Wing

375.000 € EU VAT not paid

Tel: +34 971 700844 Fax: +34 971 702275 Mobile: +34 609 622313

www.dolphin-yachts.com

Dolphin Yachts S.L.

Tel: +34 971 700844

Web: www.dolphin-yachts.com



ENGINE:

1 x 160hp Perkins 6354T

CAPACITIES:

Fuel: 2 tons Water: 2 tons

MECHANICAL EQUIPMENT:

Hydraulic Bow thruster
Water maker not serviced
Generator serviced, (5 years old)
Grey and black water tank automatic and manual controlled

ACCOMMODATION:

Berths: 10 Cabins: 5 Head: 5

Crew Berths: 1 Crew Cabins: 1

Large owner's cabin, two further ensuite double cabins, an upper and lower berth cabin and separate crew accommodation forward.

The main saloon is spacious and light with seating to port with a coffee table and aft of this is a dining table with seating for ten people with flat screen TV and Alcantara upholstery.

The two double cabins are forward with the crew beyond this. Aft of the main saloon behind the large chart table is a day heads and access to a useful upper and lower birth cabin. Behind the galley is access to the owner's stateroom with a large double berth to port and seating to starboard.

ACCOMMODATION EQUIPMENT:

5 Air conditioning units

Plasma TV

Music throughout - separately controlled

GALLEY/LAUNDRY:

2 fridges

2 freezers

Icemaker

Washing and drying machine

Hoover

NAVIGATION:

Hydraulic Autopilot

B & G and Raymarine full set of electronic navigation plus wind control, depth and speed SSB Icom Radio

2 VHF radios

Z VIII Tadios

Weather fax

DECK:

Hydraulic windlass
Hydraulic davits
Dodger and bimini (New)
Teak decks (6 Years old)
All windows and hatches resealed

SPARS & SAILS:

Dolphin Yachts S.L.

Tel: +34 971 700844

Web: www.dolphin-yachts.com



All sails hydraulic furling, GENOA, Jib, Main (5 years old) Hydraulic Boom thruster/manual Mast, boom, furlers, rigging all Randall Hydraulic control box and buttons (all new)

SAFETY:

2 liferafts

All safety equipment

TENDERS/TOYS:

Dinghy plus two outboards

SERVICE HISTORY AND CONSTRUCTION:

2020 - 2022:

- 1. Main engine full refit incl. new starter, alternator, exhaust, and the head were taken to be polished, and new gaskets everywhere.
- 2. The generator is 5 years old and was used only on 2 months trip to Greece in 2018.
- 3. Sails are 5 years old and used only on the same trip
- 4. Two of the 5 toilets are new, other 3 refitted
- 5. Of the 30 pumps onboard, 7 were refitted rest changed
- 6. All hydraulics refitted or changed including a new control panel inside and one outside in the cockpit.
- 7. Anchor winch refitted
- 8 Hydraulic pump of auto pilot new
- 9 Hydraulic pomp of davits refitted
- 10. New dodger and bimini
- 11. Boom repainted
- 12. Teak on the deck in good condition, small recaulking done
- 13. Winches all serviced
- 14. SSB radio installed
- 15. New weather fax
- 16. New tricolor and anchor light on the top of the mast

BROKERS COMMENTS:

Best five cabin layout ever seen on an Oyster 68! Quality strength performance and a design well ahead of her time.

LYING:

Spain

Dolphin Yachts S.L. Tel: +34 971 700844

Web: www.dolphin-yachts.com



The particulars presented in this brochure are based on information provided by the sellers and are believed to be correct, although we cannot be liable for any inaccuracy. A prospective buyer is strongly advised to check these particulars and where appropriate and at his own expense to employ a qualified marine surveyor and / or have an engine trial conducted which if conducted by us shall not imply any liability on our part.