



Dolphin Yachts

INTERNATIONAL YACHT BROKERS

Dolphin Yachts S.L.

Club de Mar

07015 Palma de Mallorca

Spain

info@dolphin-yachts.com



Sanlorenzo SL120A

Builder:	Sanlorenzo	LOA:	37.00m (121'4")
Model:	SL120A	Beam:	7.60m (24'9")
Year:	2022	Draft:	2.05m (6'7")
Construction:	GRP	Fuel:	19.900 Litres
Accommodation:	10 berths in 5 cabins	Water:	4.200 Litres
Designer:	Zuccon International	Engines:	2 x 2637hp MTU
Displacement:	175000 kg	Speed:	27 Knots

12.975.000 € EU VAT not paid



ENGINE:

2 x 2637hp MTU 16V2000M96L

Engine Hours: 880 aprox.

SPEED:

Top: 27 knots aprox.

Cruise: 21 knots aprox.

CAPACITIES:

Fuel: 19900 Litres

Water: 4200 Litres

Holding: Yes

MECHANICAL EQUIPMENT:

Bowthruster

Sternthruster

Stabilizers Cmc fins

Trim tabs

Generator 2x Kohler

Inverter

Watermaker

Battery Charger 24V/25A

Bilge Pump

Windlass

ACCOMMODATION EQUIPMENT:

Air conditioning 240000 BTU/h

Televisions: 4x | TV led Samsung 55" in owner cabin | TV led Samsung 85" in main salon | TV led

Samsung 43" in the two fwd guest cabins

Sat. dish – receiver KVH TV8 antenna

GALLEY/LAUNDRY:

Miele Stove Miele | Ceramic top

Gaggenau Oven

Miele Microwave

Icemaker 2x | in flybridge and main salon

Gaggenau/Miele Wine cooler (64 bottles)

Gaggenau Deep Freezer

Miele washing machine

Miele Drier

NAVIGATION:

AIS-transponder Raymarine

AIS-receiver Raymarine

Plotter Raymarine

Radar Raymarine

VHF

Depth sounder Raymarine

Compass

Rudder indicator

DECK:

Garage

Gangway

Hydraulic Swimming platform

Swimming ladder



Deck Shower

SAFETY:

Camera in engine room

Fire extinguishers

TENDERS/TOYS:

Williams Jet 565 Diesel

SERVICE HISTORY AND CONSTRUCTION:

////In lieu of Standard :

Electrical appliances

- Additional battery charger 24V 25A for generator batteries
- Cablemaster – Glendinning CM8 for shore sockets 100/125A
- Frequency converter 75kVA
- N 2 Additional sockets 24V or 220V
- N 4 Additional waterproof sockets 220V
- Additional sockets 220V in the port side owner cabin next to exit door

Navigation Electronics

- Raymarine Gold package (diff from Silver std configuration)

Alarms and controls

- CCTV IP Raymarine (no dvr): 1 fixed in the cockpit + 2 fixed on lateral passageway, 3 fixed in engine room + 1 fixed in control room
- Additional touch screen monitor 12" (Ship monitoring system)
- CCTV main deck aft camera moved to aft
- Color monitor 17" for CCTV in crew mess
- CCTV repeater in fly bridge
- Analogue rudder indicator in wheelhouse and flybridge

Electronics

- Portable control station for engines (1 connection)

Satellite and communication systems (TV SAT)

- TV-Sat KVH TV8 antenna
- Empty Radome KVH TV8

Audio and video appliances

- Gold Audio/Video Package – diff from Silver standard configuration
- 4G Wi-Fi system with harbour hotspot antenna
- TV led Samsung 55" – diff from 40" std in the owner cabin
- TV led Samsung 85" 4k – diff from 55" std – in the main salon
- TV led Samsung 43" – diff from 32" std – in the two fwd guest cabins

Household appliances

- Cooking top in ceramic glass Miele 90cm – (diff from 60cm std)
- Oven 90 cm Gaggenau/Miele (diff from 60cm std)
- Wine cooler Gaggenau/Miele 64 bottles in the main salon (OPT)
- Big Kenyon BBQ in the flybridge (OPT)
- Additional low fridge in the beach area (OPT)
- Ice maker (manual refill) in the flybridge (OPT)
- Ice maker (manual refill) in the main salon (STD)
- Additional washing machine Miele – professional – (OPT)
- Additional dryer machine Miele – professional (OPT)
- Professional washing machine Miele – (diff from std)
- Professional dryer machine Miele – (diff from std)
- Wider model of fridge and freezer by Gaggenau in the galley – (diff from std)
- Boiler 200 liters – diff from 150 liters std
- Additional low fridge in the crew dinette (OPT)
- Additional sink in the crew dinette (OPT)



Complements for the interior

Bathrooms

- 4 Rain showers (where not std) in the LD showers (OPT)
- Owner bathroom: all the shower walls with niche, plus the bench, in the shower; two lateral columns (with storage inside) of the washbasin in marble Bianco Carrara C (diff from STD).
- Lower deck showers: all the shower walls, one includes niche, in marble Bianco Carrara C (diff from STD)

Salon, Cabins, Aft Cockpit

- 2 Additional safes
- 5 Bed frame opening system with pistons (bed storage)
- 3 Electric black out shades in the owner cabin
- 3 Electric black out shades in the owner cabin
- 5 Electric curtains – diff from standard manual system, button control, in the main salon
- Wooden floor in all the owner cabin and walk in dressing (diff from std carpet)
- Wooden floor in all the lower deck cabins and lobby (diff from std carpet)
- Additional low cabinet on starboard side in main salon (for storage)
- "Loose furniture in the main salon (conversation area):
 - - L shaped sofa and n.1 pouf mod. Long island 05 by Flexform
 - -2 side tables in thick leather for the sofa Long island 05 by Flexform
 - -coffee table, mod. Jacob by Minotti
 - -1 dormeuse, custom size (40 cm longer) mod. Lucien by Flexform
 - -2 side tables mod. Nay by Minotti"
- "Loose furniture in the main salon and aft cockpit (interior dining area and exterior dining area in the cockpit):
 - -Extendible, dining table: mod. Adagio by Bauline.
 - -6 dining armchairs in the main salon and n 4 in the MD cockpit, mod. Tape "cord" outdoor by Minotti (10 units in total)"
 - Cantilevered steps, strip led underneath each step and vertical polished stainless-steel bars for the staircase in the LD lobby (diff from STD)
 - Modification of the low cabinet in the crew mess to fit sink and low fridge
 - Supply of 10 dining armchairs (6 in the main salon and n 4 in the MD cockpit), mod. Torii Nest instead of Tape Cord outdoor by Minotti (diff from the item 37 of the Annex 3)
 - Supply of a rug Santushi col. Dove in the main salon (OPT)
 - "Supply and installation of table lamps (OPT):
 - mod. Taccia by Flos, H 645 mm, base in black finish (for the bar unit)"
 - "Decorative wall panels above the headboard, with patterned leather and stainless steel inserts, strip led on top side, in the Owner cabin (diff from STD)"
 - Coffee corner between the Main salon and the Portside lobby with one shelf, strip led and cabinet on top (diff from std)
- Extra security latches for fridges/freezers

Complements for the exterior

- Dimmer package for exterior
- External inox shower column
- Beach area: Teak floor only on the lateral wings
- "Supply of 2 coffee tables 90×90 cm, mod. Mu collection by Dedon instead of 1 90×130 cm (diff from the item 46 of the Annex 3)"
- Additional chain length (n°1 length of 27,5m)
- Propspeed application on shafts, propellers and bow thruster propellers
- 8 decoders Free SAT installation & programming in the: MD saloon (the same for fly bridge), owner cabin, 4 guest cabins, captain cabin, crew mess

Flybridge

- Sun awning for the stern area of the fly
- Hard top with electric blades opening roof
- Teak floor for flybridge
- Bigger than std kitchen unit with overhanging corian countertop functioning as a bar in the flybridge, in L shape (diff from STD)



- "Loose furniture on the flybridge with rain covers (diff from STD):
- -10 dining armchairs: mod. Seax by Dedon
- -2 Loveseats: mod. Orbit by Dedon
- -1 sofa, 4-seater 245, Mu collection by Dedon
- -2 Lounge armchairs, Mu Collection by Dedon
- -1 coffee table 90×130 cm, Mu Collection by Dedon"
- "Loose furniture on the flybridge:
- - 4 bar stools: mod. Alura by Royal Botania, with rain covers (OPT)"
- Handrails from the flybridge to the bow area (one set for each side): rigid stainless-steel section (no rope), to a raised height (90 cm / 100 cm) (Diff from STD)
- "Additional netting as a safety feature for young children on the handrails from the flybridge to the bow
- area (OPT)"
- 2 subwoofers on the flybridge – to check the dimensions and feasibility
- Additional bar cabinet with sink and foldable faucet in the beach area (OPT)
- Supply of the pop-up system for the TV on the flybridge to fit the Tv on the low cabinet behind the copilot seat on the stb side

Main Deck

- Sun awning for bow area
- Full beam area awning (n°4 stainless steel poles)
- Sea stair Marquipt 9 Steps
- Disappearing stern shower
- 6 Underwater lights led (each)
- Backlit boat name letters (H. 150-300mm). Boat name: COOL (4 letters)
- Backlit boat name letters installation
- 4 big SL portholes 730×530 for guest cabins (n°2 fixed e n°2 openable) depending on boat layout
- Teak floor on bow area
- 2 smoke table with electric hi/low system with the possibility to be transformed in one dining table.

Tabletop in teak

- Aft cockpit: custom bench (with storage inside), full beam, to the aft of the cockpit, in white corian with seat and back cushions in fabric Z&R (diff from std sofa)

Engine room equipment

- Grey & Black water treatments predisposition
- Alfa laval (fuel cleaning system)
- Electric pump for engine oil change (tank not included)
- Additional 24V freshwater pump
- Tender fuel filling system with manual pump
- UV filter SH5000 for freshwater system
- Water softener Idrofats 9100
- Compressed air system with four connections: bow area, garage, engine room, flybridge
- Silver ion sterilizer for freshwater tank
- Additional 6mt tube length for tender fuel filling (in total 12mt)
- Additional Tridata Raymarine in Captain's cabin

Tender and jet ski

- Jet ski hydraulic hauling and launching system in garage

Additional

- Refrigerator and combi microwave oven in crew
- Tender Williams Diesel jet D565 diesel – Base model, standard color///// scheme, standard equipment


BROKERS COMMENTS:

The Sanlorenzo Asymmetric concept expands the saloon and allows a closer contact to the sea thanks to the full height glazing on one side and a living area on the other side that opens into a balcony, making it unbeatable in its category. Just reduced from 15M to 12.975.000€ - a rare opportunity to acquire an almost new Sanlorenzo 120A.

LYING:



Spain





Layout Plans



The particulars presented in this brochure are based on information provided by the sellers and are believed to be correct, although we cannot be liable for any inaccuracy. A prospective buyer is strongly advised to check these particulars and where appropriate and at his own expense to employ a qualified marine surveyor and / or have an engine trial conducted which if conducted by us shall not imply any liability on our part.