



Dolphin Yachts
INTERNATIONAL YACHT BROKERS

Dolphin Yachts S.L.

Club de Mar

07015 Palma de Mallorca

Spain

info@dolphin-yachts.com



Princess Riviera 46

Builder:	Princess	LOA:	14.33m (47'0")
Model:	Riviera 46	Beam:	4.27m (14'0")
Year:	1991	Draft:	0.61m (2'0")
Construction:	GRP	Fuel:	1.400 Litres
Accommodation:	6 berths in 2 cabins	Water:	400 Litres
Designer:	Builder	Engines:	2 x 460hp Caterpillar

105.000 € EU VAT paid



ENGINE:

2 x 460hp Caterpillar (2008)

Engine Hours: 200 aprox.

CAPACITIES:

Fuel: 1400 Litres

Water: 400 Litres

MECHANICAL EQUIPMENT:

Eberspaecher heating

Air conditioning

Generator 7kw 1500 rpm (2010) 22 hours (11/2/2013)

ACCOMMODATION:

Berths: 6

Cabins: 2

Head: 2

Crew Berths: 0

Crew Cabins: 0

Master cabin with large double berth with stowage below, large wardrobe, dressing table incorporating hinged mirror, two opening ports, deck hatch with vent, reading lights, tinted mirror, door to access toilet/shower compartment

Heads with Jabsco sea toilet, shower with electric pump out, mirror, wash basin, storage locker

Aft cabin with two full length single berths, wardrobe, dressing table, individual lights

Saloon with large U-shaped settee with stowage below, 2-person settee to port, hi-low table which converts to double berth

GALLEY/LAUNDRY:

L-shaped galley

Waeco fridge

AEG oven

Gaggenau vitroceramic hob

Extractor fan

Storage + bar

Worktop

Twin bowl s/s sink with hot/cold mixer tap

NAVIGATION:

Raymarine 240E VHF

Raymarine C80 GPS plotter

Raymarine ST 7001 autopilot

Raytheon RL 70C pathfinder radar

Echosounder

Speed log

DECK:

Cockpit with central section of cockpit containing dining area with folding table and L-shaped seat opposite, seat convertible into sun bed in the aft section of cockpit

BROKERS COMMENTS:

This **Princess Riviera 46** has recent electronics, new VHF, new generator, new air conditioning, new toilets and new engines (2009). Spanish flag.



LYING:
Spain





The particulars presented in this brochure are based on information provided by the sellers and are believed to be correct, although we cannot be liable for any inaccuracy. A prospective buyer is strongly advised to check these particulars and where appropriate and at his own expense to employ a qualified marine surveyor and / or have an engine trial conducted which if conducted by us shall not imply any liability on our part.