

Dolphin Yachts S.L. Club de Mar 07015 Palma de Mallorca Spain info@dolphin-yachts.com



Clelands shipbuildings Custom TSDY

33.83m (111'0") Builder: Clelands shipbuildings LOA: Model: **Custom TSDY** 6.74m (22'1") Beam: 2.77m (9'1") Year: 1960 Draft: Construction: Steel/Alum 39.150 Litres Fuel: Accommodation: 8 berths in 4 cabins 11.700 Litres Water: Frederick R. Parker 2 x 700hp MAN Designer: Engines:

Displacement: 173 tons (GRT) Speed: 13 Knots

1.500.000 € EU VAT paid

Tel: +34 971 700844 Fax: +34 971 702275 Mobile: +34 609 622313 www.dolphin-yachts.com

Dolphin Yachts S.L.

Tel: +34 971 700844

Web: www.dolphin-yachts.com



ENGINE:

2 x 700hp MAN

Engine Hours: 1500 aprox.

SPEED:

Top: 13 knots aprox. Cruise: 10 knots aprox.

CRUISE RANGE:

5000 nautical miles

CAPACITIES:

Fuel: 39150 Litres Water: 11700 Litres

MECHANICAL EQUIPMENT:

Generators 2 X Onan 45 kw 1 X Onan 30 Kw

Stabilizers VOSPER fins

Water Maker - Horizon Seafari 300 LPH

ACCOMMODATION:

Berths: 8 Cabins: 4 Head: 4

Crew Berths: 5 Crew Cabins: 3

4 cabins for 8 guests - Separate Full Beam Master cabin in the lower deck fore with en suite, VIP cabin plus two twin cabins

Crew Accommodation

Captain + 4 crew in 3 cabins in the lower foredeck

NAVIGATION:

Simrad, Radar, GPS

2 Icon VHF

BROKERS COMMENTS:

Originally built by Cleland's in 1960 the classic gentleman's yacht underwent a major refit in 2005 with new engines, generator and interior. She s offers accommodation for 8 guests in 1 master, 1 VIP and 2 twin cabins. Her boat deck features a modern covered bar area, as well as an al fresco dining table. Together with fin stabilizers and compliant with ABS class requirements for the construction, she would be the perfect vessel to explore remote places anywhere on the planet. Spanish Matriculation tax paid.

LYING:

Dolphin Yachts S.L. Tel: +34 971 700844 Web: www.dolphin-yachts.com















Dolphin Yachts S.L. Tel: +34 971 700844

Web: www.dolphin-yachts.com



The particulars presented in this brochure are based on information provided by the sellers and are believed to be correct, although we cannot be liable for any inaccuracy. A prospective buyer is strongly advised to check these particulars and where appropriate and at his own expense to employ a qualified marine surveyor and / or have an engine trial conducted which if conducted by us shall not imply any liability on our part.